

November 21, 2002

Remington Arms Company, Inc.  
Ilion Firearms Plant  
Attention: BL Safety Program  
14 Hoefler Avenue  
Ilion, NY 13357

Dear Sirs,

I am sending my Remington Mohawk - 600 for the safety retrofit, which falls under the Remington Safety Repair program.

**Problem:**

While unloading live ammunition and the weapon not on safe, the weapon is prone to discharge without touching the trigger. Additionally, multiple shots at game or multiple target shots, the weapon is prone to discharge without touching the trigger, while chamber the next round.

**Action Required:**

My understanding is the Remington Company is aware of this condition and will safety retrofit the weapon by replacing the trigger mechanism; and the weapon will also be enabled to unload ammunition while on safe. The Remington website states this is a "no charge" procedure to the customer.

Please do not increase the trigger "pounds of pull".

**My Logistics:**

**Address:**

Ronald Ibarra  
4677 Lily Avenue North  
Lake Elmo, MN 55042  
651-351-7665

**Weapon:**

Remington Mohawk-600; 308  
Serial number: 6430889


Action dirty, TA  
Attended adjustments  
Install new TA, clean  
action - update per  
current procedures. w/c

FCS 11/26/02

**Thank You**

I am available for any further questions. I also love my Remington 700 and 11-87.  
Thank you for your support and quality weapons.

Yours truly,

  
Ronald Ibarra

Serial  
Number:

**6430889**

Model: **600 MOHAWK**



**RE00056291**