

REPAIR GUN UPDATE FUNCTION: E (N)EXT (P)REV (U)PDATE (I)NQ (E)XACT 07/20/94
ENTER REPAIR NUMBER -----> 9412547 08 47 03
SERIAL NO: 251152 NEW SERIAL NO: MODEL: 700
FROM: (CUST NUM: 095638) JONASENKEN GA/CAL: 30-06
JONASEN, KENNETH N. TYPE: ADL
P O BOX 111 ACCESSORIES:

ULM MT 59485

SHIPPED TO:
JONASEN, KENNETH N.
801 SECOND STREET SOUTH

DATE CODES: RN 11-66

OTHER ACCESSORIES:
L/STUDS

GREAT FALLS MT 59401
COMMENTS:

DATES: TO FROM
RECEIVED 04 08 94 GALLERY 05 25 94 06 07 94 ENTERED BY: FPS
OPENED 04 11 94 PROD SERV 05 19 94 05 24 94 REPAIRMAN: CC
ESTIMATED 06 17 94 TAG GUNS 00 00 TYPIST:
PROMISED 00 00 00 REJECTED 00 00 CORRESPONDENT:
GO AHEAD 00 00 00 CASH RECEIVED:\$ 0.00 BILL TYPE: D
SHIPPED 00 00 00
BILL TYPE PF1=VIEW DETAIL PF2=REPRINT R&E PF3=PRINT R&E PF5=CUST MAINT

REPAIR NUMBER: 9412547 CHARGE (AWAIT RESP) EST/LETTER LSTD 07/20/94
CUSTOMER NAME: JONASEN, KENNETH N. 08 47 41

REQUEST: GUN FIRED ON TWO SEPARATE OCCASIONS WHEN THE SAFETY WAS
PUSHED FORWARD.

MAIN FAULT: ---IF QUOTE IS NOT ACCEPTED, AN UNSAFE LETTER WILL BE SENT--
UNABLE TO DUPLICATE CUSTOMERS CONCERN AS REC'D.BOTH OVER-
TRAVEL & LBS. PULL SCREWS HAVE BEEN ADJ. OUTSIDE FACTORY. WE
DO NOT RECOMMEND THAT THE TRIG BE ADJ. OUTSIDE FACTORY. EX-
CHANGE TRIG ASSY. AT A SPECIAL PRICE AS A GESTURE OF GOODWILL
-HEADSPACE FOUND TO BE AT EXTREME MAX, QUOTE FOR RESETTING.

PARTS: \$ 30.50 1 26345 TRIGGER ASSEM RH
\$ 20.00 19900001 SERVICE CHARGE
\$ 5.00 19900004 CLEAN
\$ 5.00 19900005 TEST
\$ 75.00 19900002 REPAIR LABOR
LABOR: \$ 0.00 TRIGGER PULL MEASURED 3 3/4 TO 4 3/4 LBS. AS REC'D.
\$ 0.00 SEAR LIFT WAS .008
\$ 0.00 STOCK ASSY. MARRED
\$ 0.00 CC/HAR

REPAIRMAN'S INITS: CC NUM OF WKS: 04 CORRESPONDENT'S INITS:
TOTAL VALUE:\$ 140.50 PF1 = INQ PF2 = ESTIMATE
NO MORE DATA AVAILABLE FOR THIS REPAIR

*Apparently we did work
prior to Go Ahead!*

*60.50 quoted 28.00 incl
SHIPPING*