

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-19994

FMS

CUSTOMER ORDER NO.

ATTN: JACK KAST

Set up file

DATE RECEIVED
06/28/94DATE OPENED
06/29/94DATE CODE
WS 8-69SERIAL NUMBER
6263496

NEW SERIAL NUMBER

MODEL AND GRADE
700 7MM MAG

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

JACKSON, MIKE
1042 WILLOW CREEK RD.
A111-173
PRESCOTT

AZ 86301

SHIP TO:

JACKSON, MIKE
1042 WILLOW CREEK RD.
A111-173
PRESCOTT

AZ

86301

CUST NO: 099377 C.O.D.

ACCOUNT NUMBER

063103

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

6/29/94

* Stock glass bedded
* Trigger screw sealant appears too
clear for vintage of gun?
*

REPAIR CHARGE

20

EXCISE

TAX

INSURANCE

UPS

8

PARCEL POST

TOTAL

\$28.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

Find two different times when bolt was closed

TRIGGER GROUP

B2

E1

F1

BOLT ASSY.

see letter for details

E2

F2

BARREL ASSY.

B4

D1

E3

F3

REC. ASSY.

B5

D2

E4

F4

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Mfg 8-69 Unable to duplicate customer concern as recd. DISASSEMBLY
REVEALED THAT SEAR, TRIGGER, TRIGGER CONNECTOR AND TRIGGER HOUSING WERE
ALL GUMMED UP WITH SOLIDIFIED SUBSTANCE 'PROBABLY OLD OIL' and did
NOT WORK FREELY which may have been CAUSE OF CONCERN under
different conditions. Metal parts only require a light film of light
oil to prevent rust. See new owners manual enclosed. Exchange
Trigger Assy. at special price as a gesture of good will AND TO
Restore customers confidence in rifle

COMMENTS

Trigger pull increased 3 1/4 to 3 3/4
lbs as recd. sear lift was .008

Firing pin and spring rusty

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PS03408