

file has been setup
REPAIR GUN UPDATE FUNCTION: I (N)EXT (P)REV (U)PDATE (I)NQ (E)XACT 02/18/94
ENTER REPAIR NUMBER -----> 9401049 12 48 43

SERIAL NO: C6773047 NEW SERIAL NO:
FROM: (CUST NUM: 013971) JAMESDISCO
JAMES DISCOUNT DRUGS--
6TH ST

MODEL: 700
GA/CAL: 22-250
TYPE: VS
ACCESSORIES: W/STUDS
SCOPE BASE

BAY SPRINGS
SHIPPED TO: *601-764-4342* MS 39422

DATE CODES: BN 1-93
OTHER ACCESSORIES:

COMMENTS:

DATES:	TO	FROM	
RECEIVED 01 07 94	GALLERY 02 17 94	00 00 00	ENTERED BY: FPS
OPENED 01 10 94	PROD SERV 02 15 94	00 00 00	REPAIRMAN: REF
ESTIMATED 00 00 00	TAG GUNS 00 00		TYPIST:
PROMISED 00 00 00	REJECTED 00 00		CORRESPONDENT:
GO AHEAD 00 00 00	CASH RECEIVED:\$	0.00	BILL TYPE: D
SHIPPED 00 00 00			

BILL TYPE PF1=VIEW DETAIL PF2=REPRINT R&E PF3=PRINT R&E PF5=CUST MAINT

REPAIR NUMBER: 9401049 CHARGE (AWAIT RESP) R & E GENERATED 02/18/94
CUSTOMER NAME: JAMES DISCOUNT DRUGS 12 50 18
=====

REQUEST: "WILL NOT COCK IN THE FIRE POSITION, WHEN SAFETY IS MOVED
FROM FIRE POSITION IT FIRES ON ITS OWN"

MAIN FAULT: UPON RECEIPT RIFLE INOPERATIVE - EXAMINATION REVEALED THAT
ALL 3 TRIGGER ADJUSTMENT SCREWS HAVE BEEN TAMPERED WITH
OUTSIDE THE FACTORY. ENGAGEMENT OUT OF OUR SPECIFICATION -
DATE OF MFG: 01-93

PARTS: \$ 25.00 1 26345 TRIGGER ASSEM RH
\$ 0.00 19900005 TEST
LABOR: \$ 0.00 REPLACE COMPLETE TRIGGER ASSEMBLY AT 1/2 NORMAL
\$ 0.00 REPLACEMENT COST, AS GESTURE OF GOODWILL -
\$ 0.00 NEW TRIGGER ASSEMBLY WILL BE PROPERLY ADJUSTED
\$ 0.00 AND SEALED.
\$ 0.00 REF/HAR

2/18/94 - Changed N/C as gesture of good will - Customer had
REPAIRMAN'S INITS: REF NUM OF WKS: 00 CORRESPONDENT'S INITS:
TOTAL VALUE:\$ 33.00 PF1 = INQ PF2 = ESTIMATE
NO MORE DATA AVAILABLE FOR THIS REPAIR

Hand in letter - signed with A.J. & double action ?

A.J. Program
601-789-5194
R-9401049

Allet Bros
J.C.
2/12/93