

Repair Order Number



Repair Order Number RE00089052	Description/Serial Number ML008520	Repairman - Robert Frink Date Received - 12/6/2004
Account # - R-	Model 700ML Center Fire Caliber: 54 SS	Estimate Date - Current Date - 12/10/2004
Customer KENNEDY MACHINE TOOL EN KENNEDY 8201 N ST RD 9 ALEXANDRIA, IN 46001 US		Return To KENNEDY MACHINE TOOL EN KENNEDY 8201 N ST RD 9 ALEXANDRIA, IN 46001 US
Phone (H) (765)-617-4777 XCELL Phone (W) (765)-724-2225 XWK		Fax Email

Reported		Problems Found	
M992	FIRE WHEN SAFE RELEASED	M123	FORWARD TO PRODUCT SERVICE F

<u>Material #</u>		<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part						
F99294		700 ML SS TRIG ASSB	1	1	0	Y
Part Total:			1	1	0	
Service						
4000104		ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000118		GR-CLEAN	1	1	0	Y
Service Total:			1	1	0	

Condition	Nipple and firing pin assembly not of our manufacture.				
ProblemNotes	Connector is broken. Replace trigger assembly and check over completely at no charge.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date