Remington Fire Arms 14 Hoefler Ave. Iliol, NY 13357

Attn: Ray Egland

I am writing in regard to a miss fire with my rifle. I was pushing the safety forward and the rifle miss fired. I was using pyrodex 120 grain pellets. The bullet was a powerbelt .54 caliber. The rifle was fired one time with this set-up. The next load was when the miss fire took place. The spring is enclosed inside the rifle box but packaged separately.

I can be reached by cell phone 765-617-4777 or my work number is 765-724-2225.

Thank you,

Ben Kennedy Ben Kennedy

connector is broken over producted of 1/c replaced of 230145

1007 4013

12/7

Production Machining • Jigs • Fixtures • Special Machines Luftiple Winner of the State of Indiana Quality Improvement Award



Ben Kennedy, Owner

8201 North State Road 9 Alexandria, Indiana 46001 Phone 765-724-2225 Fax 765-724-2247

Email kennedy.ben@kennedymachine.com

ENNEDY MACHINE TOOL INC

Teign ML008520

Model: 700ML



RE00089052