



TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00087270	Description/Serial Number E6798494 REPLACEMENT S6461733	Repairman - Dale Lewis
Account # - R-	Model 700 Center Fire Caliber: 300 REM ULTRA MAG BDL	Date Received - 11/3/2004
Customer JAMES KEENER 65 MEL KEENER ROAD HIGHLANDS, NC 28741 US		Estimate Date - Current Date - 11/19/2004
Phone (H) (828)-526-2928		Return To JAMES KEENER 65 MEL KEENER ROAD HIGHLANDS, NC 28741 US
Phone (W)		Fax Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	FIRED WHEN TAKING OFF SAFE	M178	TRIG ADJ SCREWS RESET, CANNOT

Repair					
Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000254	GR-FIREARM REPLACEMENT	1	1	0	Y
Service Total:		1	1	0	

ProblemNotes all three trigger adjustment screws have been readjusted outside of factory and resealed with a pink sealent...exchange rifle for m/700 bdl ss 7 mm saum ramac# 26434 n/c as a gesture of good will

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date