

Repair Order Number



Repair Order Number RE00081911	Description/Serial Number E6286283	Repairman - Dave Dunkel
Account # - R-	Model 700 Center Fire Caliber: 375	Date Received - 6/14/2004
	HAND H MAG BDL	Estimate Date -
		Current Date - 6/25/2004
Customer DON KROHN 10961 KASILOF BLVD ANCHORAGE. AK 99516 US		Return To DON KROHN 10961 KASILOF BLVD ANCHORAGE. AK 99516 US
Phone (H) (907)-777-3471		Fax
Phone (W)		Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	PROBLEM WITH SAFETY	M237	INSTALL NEW BOLT ASSM

Repair					
Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F17017	700 EJECTOR	1	1	0	Y
F17019	700 EJECTOR SPRING	1	1	0	Y
F22040	700 FIRING PIN ASSB L/A	1	1	0	Y
F26345	700 TRIG ASSB RH	1	1	0	N
F27341	700 EXTRACTOR RIVET MAGNUM	1	1	0	Y
F33273	700 BOLT ASSB L/A MAG CS F1	1	1	0	Y
F94555	700 EJECTOR PIN (SPIROL)	1	1	0	Y
F97322	700 EXTRACTOR MAGNUM	1	1	0	Y
Part Total:		8	8	0	
Service					
4000119	GR-TEST	1	1	0	N
4000294	GR-CHECK TPA	1	1	0	Y
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	N
4000116	GR-LABOR	25	25	0	N
4000117	GR-PROOF	1	1	0	N
4000118	GR-CLEAN	1	1	0	N
Service Total:		29	29	0	

Condition	Date of Mfg: June 1996 Stock has been Bedded outside of Factory Ejector is Froze up in Gallery-Replace Bolt Assy at N/C				
Problem/Notes	The Trig and Inside Trig Plate are Rusty preventing proper return of Trigger. Replace Complete Trigger Assy, Firing Pin, Clean Action. Properly Lube and Function Test at 1/2 MSP per F. Suprty				
Repairman	Pro Note: Return Ammo to Service for Stock to Customer	Target	Pattern		
Gallery Tester	Date	Date	Date	Date	Date