

**DATA-GRAPHICS, INC.**

1251 Stagfield Road  
ASHLAND, VIRGINIA 23005

JACK KAST  
MINGTON ARMS COMPANY, INC.  
HOFER AVENUE  
ION, NY 13357

(815) 895-3558

Illion, NY 13357

**RAPPAHANNOCK  
DUCK HUNTING GUIDES**



ALEX KUBALA  
NORM KUBALA



STAGFIELD ROAD • ASHLAND, VA 23005 • (804) 798-3606  
SPECIALIZING IN DIVING DUCKS

Dear Mr. Kast:

Confirming our telephone conversation of 1/18/95, let me explain my predicament.

My son and I operate a Duck/Goose Hunting Guide Service in Virginia. We hunt virtually every day of the season. We purchased two SP-10 Magnum Autoloading shotguns prior to this season.

Our experience with the SP-10's up until now was extremely positive - no equipment malfunctions and terrific stopping power on ducks and geese. However, on Monday, January 16, 1995 the problems started. While rising to stand for a shot in the duck blind, my gun - serial No. RM 014927 bumped against the front of the blind and fired. Fortunately, I was on the left side of the blind and other incident occurred.

On 1/18/94 while sitting in a goose blind, I moved the same gun from one slot to another. When the butt end touched the floor, the gun fired and blew a corner off of the blind. It about scared me to death. Both times the safety was "on."

Jack, I don't abuse my guns, but I don't baby them either. I require 100% safety performance. I will never shoot this gun again! I would like either a replacement gun or a refund.

*Jack  
The Fired shell  
did not eject in  
either instance  
Norm*

Thank you in advance for your consideration.

Sincerely,

*Norm Kubala*

Norm Kubala

P.S. Jack, if you can come up with a couple of improved cylinder choke tubes for the SP-10, this ole boy from Newport sure would be pleased.

REV. 1/84