

RECEIVING AND ESTIMATING REPORT

COMMENTS

*Product Service*ORDER
R 94-24965INITIAL
FPS

CUSTOMER ORDER NO.

DATE RECEIVED
08/29/94DATE OPENED
08/30/94DATE CODE
DS 9-69SERIAL NUMBER
6275765

NEW SERIAL NUMBER

MODEL AND GRADE
700 30-06

BDL

ACCESSORIES

W/STUDS

SCOPE MNTS

SCOPE BASE

L/SIGHTS

FROM:

KILLOUGH, KEN
8456 DOAR RD
AWENDAW

SC 29429

SHIP TO:

KILLOUGH, KEN
8456 DOAR RD
AWENDAWSC
29429

CUST NO 102489 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☒ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARREDREPAIR CHARGE *28.00*

EXCISE

TAX

INSURANCE

UPS *8.00*

PARCEL POST

TOTAL *28.00*

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

E1

F1

BOLT ASSY.

B3

BARREL ASSY.

B4

D1

E3

F3

REC. ASSY.

B5

D2

E4

F4

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

We could not duplicate the customer concern. However, examination revealed that the sear has been removed from the rear engagement screw, and the sear appears to have been replaced on the adjustment screw.

PARTS

COMMENTS

Replaced the correct trigger member and clean the contact 1/2 normal adjustment set, as a function of good work.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PS03644