

Jack Landon, Jr.  
120 Paradise Park Rd.  
Sheridan, WY 82801  
307-672-8431  
[jlandon@fiberpipe.net](mailto:jlandon@fiberpipe.net)

Remington Arms  
14 Hoefler Ave.  
Ilion, N.Y.  
13357

*Date Code  
XD 12/71*

Attn. B.L. Safety Program

Dear Sir or Ms.,

Enclosed is my model 700, .243 sent for the safety modification program to the bolt-lock.

*7* Years ago this rifle fired when the safety was released so that it could be unloaded. I thought perhaps the trigger had been partially depressed before switching the safety off. It has not done it while in my possession since, though my brother may have had such an incident and he alerted me that he had read that it could happen.

Thank you for your program and making this rifle more safe.

Sincerely,

*Jack Landon, Jr.*

Jack Landon, Jr.

Enclosed: Check # 8182, for \$20

*8/6/02 Action & trig assem. Covered with dust & heavy sticky substance - Poorly maintained*

*Replace trig assem  
\$20.00*

*Go ahead*

*1007  
4015*

*49* *Serial Number:* **6462935**

Model: **700**



**RE00049887**