


Serial
Number:

6667877

Model: 700



RE00047467

Could not duplicate:

Action dirty, TA
Coated with sticky
residue.

Clean action &
Install new TA under
Bolt lock modification program

Quote customer \$20.00.

FCS 6/5/02

Remington Safety Concern

In response to reports of accidental firing on release of the safety on its most popular rifle, Remington Arms Company is inviting owners of pre-1982 Model 700s to send those rifles to the factory, or to an authorized Remington repair center, for modification. The change will make it possible to open the bolt without moving the safety to the "off" position. To know whether your rifle is one of those in question, try opening the bolt of your unloaded gun, as if to eject a cartridge, while the safety is on. If it won't open, it's pre-1982. For details, phone 1-800-243-9700. Visit Remington's website, www.remington.com, to review the Ten Commandments of Gun Safety and obtain other advice on avoiding accidental firing.

*Compiled and edited by Lee
Cromrich and Don Burgess.*

Lauren
12957 NE 39th ST.
Bellevue, WA 98005