

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700
Madison, NC 27025-0700

Parts/Repairs 800-243-9700
Fax 336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00045084 Account # - R-	Description/Serial Number 6231818 Model 700 Center Fire Caliber: 243 ADL	Date Received - 4/25/2002 Estimate Date - 4/22/2002 Current Date - 4/29/2002
Customer OSCAR LEMEN 16520 N MERRIMAC RD CULPEPER, VA 22701 US	Return To OSCAR LEMEN 16520 N MERRIMAC RD CULPEPER, VA 22701 US	
Phone (H) (540)-948-4211 Phone (W)	Fax Email	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FO
M993	FIRES WHEN SAFE IS REMOVED	M238	CLEAN & INSPECT
		M239	REPLACE TRIGGER ASSEMBLY

Technician's Comments	
ProblemNotes	Altered adjustments. Clean and install new trigger assembly under Bolt Lock Modification program. FLS 4/18/02.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part	Total:	1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000118	GR-CLEAN	1	Y
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service	Total:	23	


9 LBS 1 OF 1

REXINGTON ARMS CO INC
800 243-9700
14 HOEFER AVE
ILION NY 13357

SHIP

TO:

OSCAR LEMEN
16520 N MERRIMAC RD
CULPEPER VA 22701-7239




VA 228 9-10



UPS GROUND

TRACKING #: 1Z 114 813 03 1187 6334



BILLING: PREPAID

INV#: RE00045084

ASC 3.70 J69K/J64K 14.0 01/2002