

**Licking Valley Armory**  
Oak Hill Rd, RR #4 Box 290  
Falmouth, Kentucky 41040



**NRA Life Member**  
FFL #61-33040  
Bus. (606) 654-2777


1/12/94

Remington Arms Co., Inc.  
Attn, Arms Service Section  
14 Hoefler ave  
Ilion, New York. 13357

The Remington 700 rifle was bought by my customer on August of 1993. The rifle was range tested and zeroed in, but on his hunting trip the malfunction occurred. He said that when he chambered a round the rifle discharged taking some skin off his thumb. "the firearm was on safe"! thinking that somehow he might have taken the safety off, he rechambered a round paying more attention to detail: "gun on safe" he observed that the firing pin was moving in the firing position denting the primer slightly.

The gentlemen brought the firearm in my shop for service, because he trusted my work on his firearms. I advised him that I should contact Remington service center, since the rifle is under warranty and I am not a Remington warranty station agent at this moment. Per our telephone conversation of 1/12/94, I am shipping you the Remington 700 BDL synthetic stocked rifle in .300 Wby. cal serial # C 6521903 for repair.

Yours Very Truly

  
Jacques H Capon  
Gunsmith

DEALER IN MILITARY  
Uniform, Edge Weapon  
Head Gear, Accoutrements  
War Relics



FFL #61-33040  
Bus. (606) 654-2777  
BILL, JACQUES  
JEAN PAUL

**LICKING VALLEY ARMORY**

Oak Hill Rd., RR #4 Box 290  
Falmouth, Kentucky 41040

JACQUES H. CAPON, Master Gunsmith  
20 Years Experience  
Stock Work, Customizing  
Bluing, General Repair

NRA Life Member