

COMMENTS

FROM: LEWIS ARMS
1575 HOOKSETT
HOOKSETT, NH 03106

SHIP TO: LEWIS ARMS
1575 HOOKSETT
HOOKSETT, NH 03106

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	CLEAN/TEST	FROM DATE	ESTIMATED	VIA
						UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

Problem with safety

MAIN FAULT
Tugger assembly rusted from sealant on some - internal
tugger joints not moving freely, nor properly

PARTS		REPAIRMAN					
		No glass trigger assembly at no-charge, as gesture of good-will					
		REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
		GALLERY TESTER	DATE	DATE	DATE	DATE	DATE