

RECEIVING AND ESTIMATING REPORT

COMMENTS

ATTN: FRAN COLE

INITIAL: **FPS** CUSTOMER ORDER NO. **011308**

| | | | | | |
|----------------------------------|--------------------------------|------------------------------|----------------------------------|--|----------------------------|
| DATE RECEIVED 11/20/90 | DATE OPENED 12/03/90 | DATE CODE EJ 10-89 | SERIAL NUMBER C6448677 | MODEL AND GRADE 700 7MM LH_BDL | ORDER R 90-31195 |
|----------------------------------|--------------------------------|------------------------------|----------------------------------|--|----------------------------|

ACCESSORIES **M/STUDS** SCOPE BASE **L/SIGHTS**

FROM:

**LIVINGSTON SPT CENTER
5589 E H-36 CHILSON RD
LAKELAND, MI 48143**

SHIP TO:

**LIVINGSTON SPT CENTER
5589 E H-36 CHILSON RD
LAKELAND, MI 48143**

| | | | | | |
|----------------|--------------------|--|------------|-----------|----------------|
| ACCOUNT NUMBER | ACCOUNT NUMBER N/C | WRITE <input type="checkbox"/> CLEAN/TEST | PROM. DATE | ESTIMATED | VIA UPS |
|----------------|--------------------|--|------------|-----------|----------------|

| | | | | | |
|---------------|-----|-----------|-----|-------------|-------|
| REPAIR CHARGE | TAX | INSURANCE | UPS | PARCEL POST | TOTAL |
|---------------|-----|-----------|-----|-------------|-------|

GUN CONDITION:

☒ **LIKE NEW**

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

"Customer tells me that on three separate occasions that gun has fired when safety was moved to the fire position."

No fault found - cannot duplicate complaint. Trigger assembly and safety function properly. Trigger pull somewhat heavy at 6 lb. less left. 011

PARTS

Offer to return w/ 200.00 as is, if it will fully restore faith in the w/ we will install a new trigger w/ at a normal price, as a gesture of good-will

| | | | | | |
|----------------|-------|-------|------|--------|---------|
| BERNARD | PROOF | CLEAN | TEST | TARGET | PATTERN |
| GALLERY TESTER | DATE | DATE | DATE | DATE | DATE |