

RECEIVING AND ESTIMATING REPORT

COMMENTS
ATTN: JIM STEKL

INITIAL
FPS CUSTOMER ORDER NO.

DATE RECEIVED
02/13/91

DATE OPENED
02/21/91

DATE CODE
PY 6-74

SERIAL NUMBER
6760251

MODEL AND GRADE
700 270 WIN

ORDER
R 91-05086

ACCESSORIES

L/STUDS

FROM:

LEWIS, D A
18130 ALTA VISTA
BUENAVISTA

CO - 01211

SHIP TO:

LEWIS, D A
18130 ALTA VISTA
BUENAVISTA

CO
01211

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☒ MARRED

CUSTOMER'S REQUEST

"are discharged when I closed the chamber on a live round"

MAIN FAULT

As reported, the trigger would not retract if the bolt stop was nearly inoperative. Inspection revealed that the trigger assembly was contaminated with a sticky residue across the bolt stop. Internal trigger parts are not moving freely. Trigger pull 5 pounds; rear left .003". Right has not been properly maintained and cleaned.

PARTS

Clean present trigger assembly, if possible; if not, offer replacement trigger assembly but $\frac{1}{2}$ removal cost, as gesture of good-will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE