

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS					
DATE RECEIVED 03/07/91	DATE OPENED 03/11/91	DATE CODE RQ 11-78	SERIAL NUMBER A6693616	MODEL AND GRADE 700 270 CLASSIC		ORDER R 91-06841			
ACCESSORIES W/STUDS									

FROM: LOCK STOCK & BARREL 11 N MAIN ST CORNELIA GA 30531	SHIP TO: LOCK STOCK & BARREL 11 N MAIN ST CORNELIA GA 30531
--	---

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED 4-1	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-------------------------	-------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: NEW SLIGHTLY WORN VERY WORN MISUSED MARRED

CUSTOMER'S REQUEST: *hammer will fire when bolt is operated sometimes without trigger being pulled*

MAIN FAULT: *Trigger assembly is contaminated with gunpowder residue - internal trigger parts are not moving freely - red safety cam is stuck to side plate of trigger assembly - firing pin will sometimes follow down when bolt is closed. I flt has not been properly maintained.*

PARTS: *We can clean present trigger assembly if possible, or we can offer to install a new trigger assembly at 1/2 normal cost, if it better restore confidence in the rifle - getting of customer good-will.*

REPAIRMAN BWT	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE