


# MOBILE SHOOTING CENTER, INC.



May 1, 1994

Re: Remington 700 ADL  
Ser. #6359050

Remington Arms Company  
Ilion, NY 13357

Gentlemen:

The enclosed Remington Model 700 ADL rifle is returned to you for repair. The problem with the gun is that if any pressure, even from the side, is exerted on the trigger and the safety if moved to the "Fire" position the gun will fire.

Please make the necessary repairs to put the gun in proper working order and return it to us for return to our customer.

Thank you for your help with this problem.

Sincerely,

A handwritten signature in cursive script, appearing to read "Joe T. Green".

Joe T. Green

710 Dykes Road

Mobile, Alabama 36608

(205) 633-8629

PS04191