

RECEIVING AND ESTIMATING REPORT

COMMENTS

to Product Service

R

ORDER
94-12201

INITIAL CUSTOMER ORDER NO.

FPS

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
04/06/94	04/07/94	DT 7-70	6358541		700 7MM MAG BDL
ACCESSORIES W/STUDS SCOPE BASE L/SIGHTS					

FROM:

MCCARTY, DARWIN
2303 ASPEN DRIVE
ALAMOGORDO

NM 88310

MCCARTY, DARWIN
2303 ASPEN DRIVE
ALAMOGORDONM
88310

CUST NO: 095516 CLO.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☒ MARRED

* Receiver area and bolt channel are glass bedded.
* other than adjustments, gun has been well maintained and clean

REPAIR CHARGE	15.00
EXCISE	
TAX	
INSURANCE	
UPS	8.00
PARCEL POST	
TOTAL	23.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Mfgn 7-70 Unable to duplicate customer complaint as rec'd. All trigger adjusting screws have been altered from factory setting. We do not recommend that the trigger be adjusted outside of the factory. Exchange trigger assy. at a special price strictly as a gesture of good will and to restore customer confidence in the rifle.

PARTS

COMMENTS

Trigger pull measured 2 1/2 * 3 lbs and break lift was .0075

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD0425 REV 1/94

PS04255