

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00046826 Account # - R-	Description/Serial Number 392688 Model 722 Center Fire Caliber: 244	Date Received - 5/22/2002 Estimate Date - Current Date - 6/5/2002
Customer MIKE MCCRAW 2026 OUNCE ST MESA, AZ 85213 US Phone (H) (480)-644-0149 Phone (W)	Return To MIKE MCCRAW 2026 OUNCE ST MESA, AZ 85213 US Fax Email	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FOR
M238	CLEAN & INSPECT	M238	CLEAN & INSPECT
		M239	REPLACE TRIGGER ASSEMBLY

Technical Comments	
Condition	BBL REC'D ALTERED.
Problem/Notes	Could not duplicate concern-Quote for New Trigger Assy at \$20.00 under Bolt Lock Safety Modification Program-Clean Action per F. Supry-Chamber Dirty & Rusty-Polish Chamber-Note: Recoil Pad & Grip Cap not of our Mfg-Stk has been Bedded outside of Factory

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000118	GR-CLEAN	1	Y
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service Total:		23	


13 LBS 1 OF 1

REXINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO:

MIKE MCCRAH
2026 QUINCE ST
MESA AZ 85213




AZ 852 9-04



UPS GROUND

TRACKING #: 1Z 114 813 03 1189 2843



BILLING: PREPAID

INV#: RE00046826

ASC 3.70 J69X/J64X 14.D 01/2002