

## SEQUENCE OF EVENTS

Date	Remington 700 ML #ML 237033	Remington 700 ML #ML236095
12/26/2002	Purchased on 12/26/02 at Shooter's Service in Livonia, MI.	Purchased on 12/26/02 at Shooter's Service in Livonia, MI.
12/28/2002	Same as # ML236095	Sight in - 15 shots total at 25 and 50 yards.
12/28/2002	Same as # ML236095	95 Grain Goex/ 300 Grain XTP/TC Sabot 50/45 #11cap
12/28/2002	Same as # ML236095	Excessive debris hitting shooter in the face.
12/28/2002	Bolt hard to open after 6-8 shots due to debris from breech plug.	Bolt hard to open after 6-8 shots due to debris from breech plug. In addition, bolt retention screw became burred & prevented the bolt from operating.
12/28/2002	Same as # ML236095	Cleaned rifle.
12/28/2002		Trigger fails to hold - gun fires when safety released.
12/30/2002		Called to Remington - advised to go to have gun serviced at W. Johnson Service Inc. 1-800-243-9700 Jason Spragley Ext. 8774.
12/30/2002	Inspection of gun at W. Johnson Service, Inc. Cost \$10.00	Delivered gun to W. Johnson Service Inc. Repair cost - \$20.00
1/10/2003	Picked up gun from W. Johnson Service Inc.	Picked up gun from W. Johnson Service Inc.
1/10/2003	Shot gun at rifle range 15-20 shots.	Shot gun at rifle range 15-20 shots.
1/10/2003	Cleaned and stored.	Cleaned and stored.
5/17/2003	Same as # ML236095	Shot gun at rifle range 15-20 shots. 80 Grain Triple 7/ 300 Grain XTP/TC Sabot 50/45 / Musket cap Sight in 25 and 50 yards.
5/17/2003	Cleaned and stored.	Cleaned and stored.
7/19/2003	Same as # ML236095	Shot gun at rifle range 15-20 shots. 80 Grain Triple 7/ 300 Grain XTP/TC Sabot 50/45 / Musket cap Sight in 100 yards.
7/19/2003		Trigger Fall Fires as stated on the repair slip.
7/19/2003	Cleaned and stored.	Cleaned and stored.