

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL FPS	CUSTOMER ORDER NO.		DATE RECEIVED 11/26/90		DATE OPENED 11/28/90	DATE CODE AD 3-77	SERIAL NUMBER A6438672	MODEL AND GRADE 700 264 WIN	BDL/MAG	ORDER R 90-30845
ACCESSORIES SCOPE BASE		L/STUDS								

FROM:	SHIP TO:
MEDENWOLD, KM	MEDENWOLD, KM
RR 1	RR 1
HANKINSON ND 58041	HANKINSON ND 58041

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 12-17-90	VIA V456729574
----------------	--------------------	--------------------------------	------------	------------	------------------------------	--------------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: *Safety needs to be changed Goes off when opening Bolt. Check B31 see if it will group.*

MAIN FAULT: *Cannot duplicate complaint - Trigger assembly and safety function properly. However, the trigger assembly has been improperly adjusted outside of factory (excessive overtravel) and the wt. of pull and overtravel screws have had the adjust removed and not replaced.*

PARTS:

- 1) Gallery Test up for accuracy*
- 2) Offer to either properly re-adjust the present trigger assembly or offer to replace trigger assembly at a minimal price as a gesture of good-will if it will better instill confidence in it.*

REPAIRMAN R/B	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE