

Dear Remington Arms Co,

the enclosed gun (serial no. 134230) has a faulty or worn trigger mechanism. It has been occasionally firing prematurely as the safety is pushed forward or the bolt is lowered to the cocked position.

The last accident occurred in my garage as I worked some handloads through the chamber. one live round went off and I was able to duplicate the premature firing on empty shell cases.

Had I not been practicing good gun safety during these premature firings a serious accident might have resulted.

I am the original owner of this gun which was purchased in 1965 or 66. It
(over)

{has been problem free until the past few hunting seasons. the gun has been used exclusively for hunting in Alaska and no more than 25 rounds per year on average are fired.

Would you please evaluate the firing mechanism on this rifle and advise me on repair.

Thank you,

JERRY A. McCRARY
P.O. Box 235
KODIAK, AK 99615