

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-25789

INITIAL CUSTOMER ORDER NO.

W/RUBBER BOOT

FPS

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/19/93	12/02/93	DN 9-66	230583		700 243 WIN BDL
ACCESSORIES W/STUDS SCOPE BASE L/SIGHTS					

FROM:

MCBRIDES GUN SHOP

C/O NBS

2915 SAN GABRIEL/30TH N LAMAR

AUSTIN

TX 78705

SHIP TO:

MCBRIDES GUN SHOP

C/O NBS

2915 SAN GABRIEL/30TH N LAMAR

AUSTIN

TX

78705

CUST NO: 006578 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

12-16-93

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

Product Service

REPAIR CHARGE 25.00

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1		
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			E2			

MAIN FAULT

Upon receipt, unable to duplicate customer concern. Rifle only 190
ammunition rounds that the action and trigger assembly have not been properly
cleaned or maintained. They are covered with dirt, rust, and heavy coating
of sticky substance.

PARTS

COMMENTS

Replace complete trigger assembly
clean action at 1/2 normal pressure
not as good as good will

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/92

PS04406