

Remington
Ilion Firearms Plant and Custom Shop
14 Hoefler Ave
Ilion, N.Y. 13357

To: Whom this is Assigned

Subject: Model 700 ADL serial no B6520621

The Story:

The Rifle was purchased on Jan 18, 1986 in the Minneapolis area. While checking out the Rifle I removed the Stock and cracked the stock on reassembly. I sent the rifle out to Remington to request a new stock which was provided and that is the stock currently on the Rifle.

I added a scope to the rifle and used it for sighting in and deer hunting in the fall. The use was about 10 to 20 rounds per season. During Deer hunting about 1994 I was loading the rifle which had been in my car overnight and was cold. When loaded I put a round into the chamber and tested the safety typically on and off. When I put the safety in the fire mode the rifle fired. I was not sure of what happened and the Remington Local Remington authorized gunsmith suggested that I had my hand in the trigger and had fired it myself. I wasn't sure and noted to him that the safety moved harder than it used to. The Frontiersman took the Rifle and looked at it. Lubricated the Safety or Trigger Mechanism and kept it for about two months. What he did was when he walked by the rifle he would pick it up and try to duplicate the failure which did not happen.

I got the Rifle back and have hunted with it for a few years. I don't always make the season it depended on work. Anyway this season I was sitting in my ladder stand with the rifle across my lap and I was looking intently at one of those early morning deer. I decided this looked pretty good and decided to take the safety off and raise the rifle so I could scope out this image and be prepared to shoot if it was real. Well it was cool about 32 degrees farenheight and when I clicked off the safety which moved hard the rifle fired. I know I did not have my hand in the trigger area as evidenced by the cut on my thumb which took the recoil of the rifle.


Back at the Camp I checked this out with Del Jacobson who owns a number of weapons and has done more extensive hunting than I and he states that the safety does not move as it does in his Remington 700 rifles.

So that's the story. Needless to say I am not real comfortable with this rifle, unfortunately it shoots real straight. Well it's in your hands.

Richard Nibbe
825 Hickory Lane
Winona, Minnesota. 55987

Serial Number: **B6520621**

Model: **700**



RE00089219

415#
3/84
could not duplicate concern
Trig set to close to guard. Safe
word off.
Install new TA
clean action w/c
Charge 230145
FCS
12/10/2004

1007
4040

12/10
3/84

415
5/84

could not duplicate concern
Trigger set to close to guard, safe
hand off.

Remington
Ilion Firearms Plant and Custom Shop
14 Hoefler Ave
Ilion, N.Y. 13357

To: Whom this is Assigned

Subject: Model 700 ADL serial no B6520621

The Story:

The Rifle was purchased on Jan 18, 1986 in the Minneapolis area. While checking out the Rifle I removed the Stock and cracked the stock on reassembly. I sent the rifle out to Remington to request a new stock which was provided and that is the stock currently on the Rifle.

I added a scope to the rifle and used it for sighting in and deer hunting in the fall. The use was about 10 to 20 rounds per season. During Deer hunting about 1994 I was loading the rifle which had been in my car overnight and was cold. When loaded I put a round into the chamber and tested the safety typically on and off. When I put the safety in the fire mode the rifle fired. I was not sure of what happened and the Remington Local Remington authorized gunsmith suggested that I had my hand in the trigger and had fired it myself. I wasn't sure and noted to him that the safety moved harder than it used to. The Frontiersman took the Rifle and looked at it. Lubricated the Safety or Trigger Mechanism and kept it for about two months. What he did was when he walked by the rifle he would pick it up and try to duplicate the failure which did not happen.

I got the Rifle back and have hunted with it for a few years. I don't always make the season it depended on work. Anyway this season I was sitting in my ladder stand with the rifle across my lap and I was looking intently at one of those early morning deer. I decided this looked pretty good and decided to take the safety off and raise the rifle so I could scope out this image and be prepared to shoot if it was real. Well it was cool about 32 degrees farenheight and when I clicked off the safety which moved hard the rifle fired. I know I did not have my hand in the trigger area as evidenced by the cut on my thumb which took the recoil of the rifle.

Back at the Camp I checked this out with Del Jacobson who owns a number of weapons and has done more extensive hunting than I and he states that the safety does not move as it does in his Remington 700 rifles.

So that's the story. Needless to say I am not real comfortable with this rifle, unfortunately it shoots real straight. Well it's in your hands.

Richard Nibbe
825 Hickory Lane
Winona, Minnesota. 55987

Serial Number: **B6520621**

Model: **700**



RE00089219