

1/26/01

Date Code 6/73

The gun fired when released slightly

Upon receipt we could not
disassemble, but did find action & trigger
assembly. The bolt stop release
(small panel) covered with brown substance.
Trigger & stop screws appear to have
been re-set.

Spine trigger assembly complete & then
action at no change produced

Change 230145