

6/3/2002

MARVIN E. POOLE
3827 DUNWOODY DR.
CHARLOTTE, NC 28215

SENT FOR REPAIR REMINGTON 700 SERIAL # 6486409

~~REPAIR---~~ SHOULD TO BE ABLE TO UNLOAD RIFLE WITHOUT
MOVING THE SAFETY.

RIFLE DISCHARGED ONCE (LAST YEAR) WHEN SAFETY WAS
MOVED TO UNLOAD --AT THE END OF THE HUNT.

PLEASE RETURN IN THE SAME BOX.

I APPRECIATE YOUR HELP.

MARVIN E. POOLE
3827 DUNWOODY DR
CHARLOTTE, NC. 28215
704-537-2361

Serial
Number:

6486409

Model: 700



RE00047894

1007
4015

6/11/02

Tuy Anam Components working sluggish

Rifle poorly maintained

Replace components Tuy Anam \$ 20.00

Quote

Quote
EU
10/71