


March 21, 1995

Gunsmith,

The enclosed Remington model 721 (30-06) serial number 44511 has a trigger problem. Once, it fired after the safety had been released and I started to rotate the bolt up to unload. Twice it fired as the safety was released. I think the rest of the gun is OK. Fix it up if it's worth it. Please advise me if there are big problems.

Thanks,


Don Plantz

Ship back to:
Don Plantz
141 Parfitt Way
Bainbridge Island, WA. 98110
(206) 842-9907

PS04828