


7/88

**PALM BEACH COUNTY
SHERIFF'S OFFICE**

RIC L. BRADSHAW, SHERIFF



93948

TRAINING BUREAU-ARMORY

SGT. JOHNNY HYDE; CHIEF ARMORER (561) 688-3593
JOHN O'ROURKE; ASSISTANT ARMORER (561) 688-4220
JOHN BRADY ASSISTANT ARMORER (561) 688-3596

Fax: (561) 688-3576

Email: hydej@pbso.org
o'rourkej@pbso.org
bradyj@pbso.org


February 24, 2005

Remington Arms Company, Inc.
Attn: Arms Service Department
14 Hoefler Avenue
Ilion, NY 13357

Serial Number:

C6227197

Model: **700**



RE00093948

Dear Sir:

Enclosed is one Remington Model 700 Rifle, caliber .308 Win., serial No. C6227197. After closing the bolt the firing pin falls when you attempt to either engage the safety or touch the bolt handle. Please inspect and repair as necessary. Request the trigger pull be set to the lowest factory setting.

After completion of repairs return the rifle to:

Palm Beach Sheriff's Office
Attn: Sgt. Johnny Hyde, Chief Armorer
3228 Gun Club Road
West Palm Beach, FL 33406-3001

Thank you for your prompt attention to this matter.

Sincerely,

John O'Rourke
Assistant Armorer

* Return cust. APT. MET.
TPA in separate comm

Trig. plate Assm. + bbl.
Not of Rem. Mfg. Fir.
Pin falls as bolt handle
is lifted. Replace TPA AT
less 22% off normal. check
over ~~and~~ safe operation
+ return. *Quox*