

REPAIR GUN UPDATE FUNCTION: N (N)EXT (P)REV (U)PDATE (I)NQ (E)XACT 03/31/94
ENTER REPAIR NUMBER -----> 9203077 13 45 54
SERIAL NO: A6346902 NEW SERIAL NO: MODEL: 700
FROM: (CUST NUM: 056921) PAYNECLAYT GA/CAL: 30-06
PAYNE, CLAYTON L TYPE: ADL
1360 GIBSON DRIVE ACCESSORIES: W/STUDS

BIRMINGHAM AL 35214
SHIPPED TO:

DATE CODES: WI
OTHER ACCESSORIES:

COMMENTS: W/LEUPOLD 2X7 SCOPE & SEE THRU SCOPE MNTS

DATES: TO FROM
RECEIVED 01 17 92 GALLERY 03 12 92 03 16 92 ENTERED BY: FPS
OPENED 01 24 92 PROD SERV 02 18 92 02 20 92 REPAIRMAN: EZ
ESTIMATED 02 26 92 TAG GUNS 00 00 TYPIST:
PROMISED 00 00 00 REJECTED 00 00 CORRESPONDENT:
GO AHEAD 00 00 00 CASH RECEIVED:\$ 0.00 BILL TYPE: D
SHIPPED 03 25 92
BILL TYPE INV PF1=VIEW DETAIL PF2=REPRINT R&E PF3=PRINT R&E PF5=CUST MAINT

REPAIR NUMBER: 9203077 CHARGE (AWAIT RESP) CREDCRD INV PRI 03/31/94
CUSTOMER NAME: PAYNE, CLAYTON L 13 46 22

=====

REQUEST: 3 TIMES, FIRED WHEN SAFETY RELEASED
MAIN FAULT: CANNOT DUPLICATE COMPLAINT AFTER MANY ATTEMPTS - REMOVAL OF
BARRELED ACTION FROM STOCK REVEALED DIRT & EXCESSIVE OIL ON
UNDERSIDE OF METAL - TRIGGER ASSEMBLY IS EXCESSIVELY OILY &
DIRTY ALSO -
DATE OF MFG: 08-88

PARTS: \$ 0.00 1 26345 TRIGGER ASSEM RH
LABOR: \$ 0.00 REPLACE TRIGGER ASSEM AT 1/2 NORMAL COST, AS A GESTURE
\$ 0.00 OF GOOD WILL -
\$ 25.00 REPAIR CHARGE -
\$ 0.00 TEST
\$ 0.00 EZ/HAR
\$ 0.00 * RETURN SCOPE & MT. IN CABINET