

File Number:	18865		Arms Service number:	64133	
Last Name:	PHOTO ART STENCIL & SIGN		First Name:	ROBERT BEELER	
Street:	701 17TH AVENUE		City:	SO. BELMAR	
State:	NJ	Zip:	07719-0127	Home Ph:	732-922-8211
Work Ph:	732-681-7300	Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1023	
Concern:	DELAYED FIRED				
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	BLM PROGRAM		Settlement Amount:	\$0.00	
Date Opened Rem:	4/7/2003	Date Opened by P/S:	4/8/2003	Caliber:	308
Date of Incident:		Date Closed:	4/8/2003	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	
Model:	700	Serial:	6413684	Date Code:	AU
RAMAC:	700	Litigation:		PreLitigation:	
Custody:		Obsolete:			
Time of Modification:	9:37 30 AM	Comments: Could not duplicate, sear sticks down and is sluggish returning to proper position due to sticky residue build-up. Install new TA. clean action \$20 under the bolt lock modification program. Customer contacted to determine type of oil being used in firearm, and to discuss cleaning and bolt lock modification program.			
Date of Modification:	4/8/2003				