

RECEIVING AND ESTIMATING REPORT

COMMENTS

Stetl

ORDER
R92-16016

INITIAL FPS	CUSTOMER ORDER NO.				
DATE RECEIVED 07/31/92	DATE OPENED 08/11/92	DATE CODE RX 11-73	SERIAL NUMBER 3685506	NEW SERIAL NUMBER	MODEL AND GRADE 700 7MM MAG LH BDL
ACCESSORIES W/STUDS		L/SIGHTS			

FROM:

ROPER, JOHN
2284 CODY ESTEY RD
RHODES

MI 48652

SHIP TO:

ROPER, JOHN
2284 CODY ESTEY RD
RHODESMI
48652

CUST NO: 064663 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 8-19-92	VIA UPS
GUN CONDITION				REPAIR CHARGE		
☒ NEW				EXCISE		
☒ LIGHTLY WORN				TAX		
☐ WORN				INSURANCE		
☐ VERY WORN				UPS		
☐ UNREPAIRABLE				PARCEL POST		
☒ MARRIED				TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	AT					
TRIGGER GROUP						
TRIGGER ASSY.					E2	F2
BARREL ASSY.				D1	E3	F3
REC. ASSY.				D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Trigger assembly is inoperative. Trigger assembly is contaminated with gunpowder residue, and safety can and other internal trigger parts all sticking to trigger assembly sub plate and are not moving. This condition appears to have resulted from improper maintenance and has all adjustments out of specification.

PARTS	COMMENTS
	Offer new trigger assembly at 1/2 normal cost as price of good one over customer's bid and affected present trigger assembly.
REPAIRMAN RBS	PROOF
GALLERY TESTER	DATE
CLEAN	DATE
TEST	DATE
TARGET	DATE
PATTERN	DATE

OFFICE COPY

RD6925 REV. 1/92

PS05069