

RECEIVING AND ESTIMATING REPORT

CUST NO: 047992 C.O.D

ENTIRE GUN IS PAINTED

CUSTOMER ORDER NO.

CEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	BDL	ORDER
20/91	08/22/91	DB-1/1	B6324614	700 308		R 91-16474
ORIES		W/STUBS	SCOPE BASE	L/SIGHTS		

ROBINSON, MARK
RT 3 BOX 181A

CAMERON
USA

MO 64429

SHIP TO:

ROBINSON, MARK
RED X MOTORE
509 NORTHLAND DR
CAMERON
USA

MO 64429

NT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					9-9-91	UPS

CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

WER'S REQUEST

ON safety is disengaged rifle sometimes fires, when closing bolt it
it discharge.
CANNOT disengage safety. However, trigger assembly has
an improperly adjusted safety sear. The sear is missing from
the trigger pull bar. The sear is at 2 1/4" over travel
sufficient to prevent action. The sear is installed in the trigger assembly
- safety lever will not move fully rearward because of contact
in stock inletting.

Send repair quotation for new trigger
assembly.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
DE					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE