

Remington.

TRACKING DOCUMENT

Repair Order Number



Repair Order Number
RE00050096

Description/Serial Number
E6725080

Repairman - Richard Hiltz
Date Received - 8/1/2002

Account # - R-

Model 700 Center Fire Caliber: 3006
ADL SYN

Estimate Date -

Current Date - 8/5/2002

Customer
REYNERSONS
10044 HOOPER RD

Return To
REYNERSONS
10044 HOOPER RD

BATON ROUGE, LA 70818 US

BATON ROUGE, LA 70818 US

Phone (H) (225)-261-4860

Fax

Phone (W)

Email

Problems

Reported

M123 FORWARD TO PRODUCT SERVICE
FOR INSPECTION

Found

M123 FORWARD TO PRODUCT SERVICE F

Repair

Material # MaterialDesc

Quantity
Needed

Quantity
From Inv

Quantity
From Kit

Warranty
(Y/N)

Service

4000104 ARMS SERV SHIPPING & HANDLING

0

0

0

Y

Service Total:

0

0

0

Could not duplicate
8/7/02 Replace trigger assembly at no charge
Set at Prod Service completely disassemble

ProblemNotes forward to product service for inspection

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date