

Remington

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700		Serial Number: 6531741	
Are you the original owner? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
Name: Pat Sheldon		Date of Purchase: 1978	
Address (no PO Boxes): 40 Brunswick Ct			
City: Iowa City		State: IA	Zip: 52240
Phone (Daytime): 319 339 9504		Fax: 319 339 9533	
E-mail Address:			
<input type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem:			
Gun did discharge once while unloading			
Quote \$20.00 for cleaning action			
and new TA under Bolt Lock Modification			
program.			
FLS 7/26/02			
Ammunition Information:			
Manufacturer: ?		Type: ?	
Other (i.e. bullet weight/type, shot size, powder):			
Handload Information:			
Powder Used: ?		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	
Firearms Care (Cleaning and Lubrication):			
Brand of cleaning solution used: ?			
How often do you clean the bore? (Months or Number of rounds) 6 months			
How often do you clean the action? (Months or Number of rounds) 6 months			
How often do you clean the trigger assembly? (Months or Number of rounds)			
Brand of lubricant used:			

Serial Number:

6531741

Model: 700



RE00049636

of rounds)

of rounds)

or Number of rounds)

endations on our web site or in our owners

EP.HTM

9/26/2001

PS05323