

Shootin Stuff
Francis M. Keeler
113 Lindale Drive
Colchester, Vt. 05446
(802) 879-6644

8/2/02

Stat Cook
P.W.
6/72

Remington Arms Co.
Arms Service Section
Ilion, NY 13357

Enclosed please find a Remington 700 BDL, 7mm magnum, Serial # 6562131 (3 pieces gun-bolt-trigger assembly).

The initial problem encountered was the gun fired when the bolt was being closed. During inspection of the problem the gun was improperly disassembled, removing the 3 trigger adjustment screws prior to removal of the sear spring. Reassembling then damaged the sear spring.

Please replace the sear spring, reassemble, adjust trigger springs, and check for proper functioning.

Thank You
Francis M. Keeler

50536

Replace complete trigger assembly \$20.00