

215-774-5463

REPAIR GUN UPDATE FUNCTION: N (N)EXT (P)REV (U)PDATE (I)NO (E)XACT 07/31/93
ENTER REPAIR NUMBER -----> 9314408 07 35 36

SERIAL NO: 328013 NEW SERIAL NO: MODEL: 700
FROM: (CUST NUM: 080530) SCHARNITZS GA/CAL: 308 WIN
SCHARNITZ, SCOTT M. TYPE:
605 BUCKINGHAM DR. ACCESSORIES: L/SIGHTS
SCOPE BASE
L/WOOD
L/FOLLOWER
L/MAG SPRING

NORTHAMPTON PA 18067
SHIPPED TO: *[Signature]*

DATE CODES: AR 3-68
OTHER ACCESSORIES:

COMMENTS: ATTN: DENNIS SANITA

DATES: TO FROM
RECEIVED 06 25 93 GALLERY 06 30 93 07 06 93 ENTERED BY: FPS
OPENED 06 29 93 PROD SERV 00 00 00 00 00 00 REPAIRMAN: REF
ESTIMATED 07 06 93 TAG GUNS 00 00 TYPIST:
PROMISED 00 00 00 REJECTED 00 00 CORRESPONDENT:
GO AHEAD 07 06 93 CASH RECEIVED:\$ 0.00 BILL TYPE: D
SHIPPED 07 09 93
BILL TYPE INV PF1=VIEW DETAIL PF2=REPRINT R&E PF3=PRINT R&E PF5=CUST MAINT

REPAIR NUMBER: 9314408 CHARGE (WORK DONE) CREDCRD INV PRI 07/31/93
CUSTOMER NAME: SCHARNITZ, SCOTT M. 07 35 48

REQUEST: RIFLE DISCHARGED WHEN SAFETY WAS MOVED.
MAIN FAULT: UPON RECEIPT RIFLE INOPERATIVE. TRIGGER WILL NOT RETRACT
EXAMINATION REVEALED THAT THE SEALANT HAD BEEN REMOVED
FROM THE TRIGGER ADJUSTMENT AND STOP SCREWS. BOTH SCREWS
BACKED OUT OF HOUSING. TRIG. PULL BELOW 2 LBS FACTORY SPEC.
RIFLE ADJUSTED OUTSIDE FACTORY. MFG. 1968

PARTS: \$ 0.00 1 26345 TRIGGER ASSEM RH
LABOR: \$ 20.00 REPLACE TRIGGER ASSEM COMPLETE AT SPECIAL PRICE
\$ 0.00 CLEAN ACTION, REQUEST TRIG PULL 3 LBS TO 3 1/2 LBS.
\$ 0.00 TEST WITH SLAVE STOCK, ETC.
\$ 0.00 REF;CM

REPAIRMAN'S INITS: REF NUM OF WKS: 03 CORRESPONDENT'S INITS:
TOTAL VALUE:\$ 20.00 PF1 = INQ PF2 = ESTIMATE
NO MORE DATA AVAILABLE FOR THIS REPAIR

Loan change N/S Safety no bolt lock 8/2/93