R. DENNIS SANITA
EMINGTON ARMS
RMS SERVICE DIVISION
4 HOEFLER AVE
ILION, N Y 13357

MR SANITA,

I HAVE NOT USED THIS RIFLE FOR A COUPLE OF YEARS AS I AM AFRAID OF IT MISFIRING. THIS HAS OCCURRED ON AT LEAST THREE OCCASIONS AND IT SEEMS TO DO SO AS YOU TAKE IT OFF OF SAFETY.

THE FIRST TIME IT SHOT A HOLE THROUGH THE FLOOR OF MY VEHICLE THROUGH THE DIL FILTER. WE ENDED UP HAVING TO WALK SOME 20 MILES TO A PHONE TO GET SOMEONE TO BRING A NEW FILTER AND DIL TO US SO WE COULD GET OUT OF THE WOODS. LUCKILY THAT WAS THE ONLY DAMAGE DONE DUE TO THE PROBLEM.

AS NOTED THIS IS A MODEL 700 25-06 WITH SERIAL NUMBER OF A6591981.

PLEASE CORRECT THIS PROBLEM AND RETURN TO THE ADDRESS LISTED BELOW. THANKS.

DAWID STANLEY

112 TEXAS AVE. (PO BOX 427) HEWITT, TX 76643

817 - 666-2451