

File Number:	20906		Arms Service number:	90954	
Last Name:	STOVER		First Name:	JACK	
Street:	973 KAIBAB TRAIL		City:	HAMILTON	
State:	MT	Zip:	59840	Home Ph:	
Work Ph:		Product Type:	F	F A T O	
Type Concern:	S	PI PD P S C	Concern Code:	1008	
Concern:	FIRED ON BOLT CLOSING				
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	BLM PROGRAM		Settlement Amount:	\$0.00	
Date Opened Rem:	1/14/2005	Date Opened by P/S:	1/14/2005	Caliber:	22250
Date of Incident:		Date Closed:	1/17/2005	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	
Model:	700	Serial:	A6713126	Date Code:	AV
RAMAC:	700	Litigation:	☐	PreLitigation:	☐
Custody:		Obsolete:	☐		
Time of Modification:	12:45:24 PM	Comments: Trigger pull set screw position altered. Trigger works sluggish due to a sticky lubrication residue. Replace TA and clean action under the bolt lock modification program - quote \$20.			
Date of Modification:	1/17/2005				