

Date: 1/17/05

By: Bruce TRAIVISSN

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: JACK STOVER

R.E. Number: 90954

Reason for inspection: FBI

FIREARM

Manufacturer: Rem. Model: 700

Serial Number: A671 3126 Date of Manufacture: 3/79

Overall external condition: Good

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: -

Adjustments/alterations: Trig. pull altered

Other: Trig. sluggish

Headspace: -

Function evaluation:

Feeding: -

Extraction/ejection: -

Trigger pull: 3.5#

Manual safety: okay - bolt lock:

Test firing results (if applicable): -

DISPOSITION

Trig. pull set screw adjusted - Trig. works very sluggish
from a sticky lubrication residue. Replace TRA & clean
action under bolt lock program R012

ADDITIONAL COMMENTS

\$20.00 work