

# RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL CUSTOMER ORDER NO.

CS

DATE RECEIVED 2/05/90 DATE OPENED 12/11/90 DATE CODE KI 5-26 SERIAL NUMBER A6306546 MODEL AND GRADE 700 243 BDL ORDER R 90-32118

ACCESSORIES W/STUDS SCOPE BASE

L/REAR SIGHT

FROM:

SMITH GUNS  
5458 PADRE STAPLES MALL  
CORPUS CHRISTI TX 78411

SHIP TO:

SMITH GUNS  
5458 PADRE STAPLES MALL  
CORPUS CHRISTI TX  
78411

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☒ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☒ MARRED

CUSTOMER'S REQUEST

*fires on safety release*

MAIN FAULT

*Found no fault - cannot duplicate complaint. Trigger and safety assembly operates properly. Trigger pull 5 1/2 pounds, over-  
"off" .008". However, trigger assembly is contaminated with  
"over amount of partially dried and wet lubrication."*

*Offer to return rifle with present trigger  
broken fly (after cleaning) or, we can  
install a new trigger assembly at  
1/2 normal cost, as a gesture of  
good-will, if it will better restore  
confidence in the rifle.*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE