

Repair Order Number



Repair Order Number RE00071130	Description/Serial Number 399242	Repairman - Bruce Travis Date Received - 10/17/2003
Account # - R-	Model 721 Center Fire Caliber: 30 06 Less STOCK	Estimate Date - 10/13/2003 Current Date - 10/20/2003
Customer LONNIE SWETT 137 SWETT ROAD P.O. BOX 15 EAST DIXFIELD, ME 04227 US		Return To LONNIE SWETT 137 SWETT ROAD P.O. BOX 15 EAST DIXFIELD, ME 04227 US
Phone (H) (207)-645-2417 Phone (W)	Fax Email	

Reported		Problems	Found
M990	SAFETY IS BROKEN	M123	FORWARD TO PRODUCT SERVICE F
M992	FIRES WHEN BOLT IS CLOSED		
M993	REPLACE TRIG ASSM / STOCK		

Material #		MaterialDesc	Repair		Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part								
F102068	700	STK ASSB ADL L/A LAM			1	1	0	N
F26345	700	TRIG ASSB RH			1	1	0	Y
Part Total:					2	2	0	
Service								
4000104		ARMS SERV SHIPPING & HANDLING			0	0	0	N
4000116		GR-LABOR			20	20	0	N
Service Total:					20	20	0	

ProblemNotes	barrel not of remington manufacture. trigger assm dirty and adjusting screws have been re-set. repair per customers instructions, charge \$20.00 for a new trigger assm. the only stock available to fit the bbl contour is the ADL brown lam stock				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date