tepair # : K12769
Received : 92/04/23

:lso See Repair # :

Sustomer: WM 813
Address: 315 A. EAST COMMERCE
Address: Return Claim Number : 01-0813-727

Sity, State Zip : BROWNWOOD, TX 76801

1ake : REMINGTON Model : 700 ADL lal/Ga : 243 Serial # : C6279986

)ate to Factory : 92/06/30 Shipping Cost : 6.13

Date Signed : F C # : D025 0908 317 F Sign : Factory Repair # : Date Returned from Factory :

Date to Customer : Insured Value : 500.00

Date AOD Signed : C Sign : C C # :

Person Inquiring :

Date of Inquiry : Pers Waiting Auth : Signer : Waiting Parts : Part Numbers : Charges :

Part Waiting On :

Amount of Charges : Jaiting On Response :

Comments : STOCK CRACKED BY BOLT. ALSO FIRES ON CLOSING OF BOLT. WHEN BOLT CLOSES IT SOMETIMES RELEASES FIRING PIN CAUSING ACCIDENTAL DISCHARGE OF ROUND.

xplanation of Charges :

Tracer Information

Date/Sent: Date/Received:

Serial Number Changed: Originally:

New :