

DEAR SIRs:

ENCLOSED IS MY REMINGTON 30.06 MODEL 700 BDL. AS I
EXPLAINED IN MY LETTER, IT HAS DISCHARGED TWICE AFTER
TAKING THE RIFLE OFF "SAFE". I PURCHASED IT USED
SO I DON'T KNOW THE COMPLETE HISTORY. I HAVE BEEN
TOLD BY FRIENDS (NOT EXPERTS) THAT THE 700 SERIES
MIGHT HAVE HAD A RECALL MANY YEARS AGO AND IF SO,
THIS MAY NOT HAVE BEEN ADJUSTED OR CHECKED OUT.
I AWAIT YOUR RESPONSE!

SINCERELY

DAVID ST. LAURENT
585 KEELING RD.
NORTH POLE AK 99705
907-488-9695 HOME
-377-5248 WORK
REMINGTON MODEL 700 BDL 30.06
SER #
AG791557