

# Remington

## Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700		Serial Number: 6477671	
Name: WALTER E. TULLOCH		Date of Purchase: IN GERMANY JUNE 1972	
Address (no PO Boxes): 1495 CENTENNIAL DR			
City: MTN. HOME		State: IDAHO	Zip: 83647
Phone (Daytime): 208-587-5957		Fax:	
E-mail Address:			
Please describe your problem: SENDING RIFLE BACK FOR SAFETY MODIFICATION PROGRAM ALSO THIS RIFLE HAS FIRED ON TWO OCCASIONS WHEN SAFETY HAS BEEN MOVED TO FIRE POSITION			
Additional Information: (Ammo type, brand, handload specifications, etc.)			
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			
<p>ⓈWARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p> <p>:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.</p>			

Date Code  
DY  
9/71

Serial  
Number:

6477671

Model: 700



RE00055912

Could not duplicate - sticky  
residue - bolt release sticks  
Quote \$20 for new TA  
and cleaning action under  
boltlock modification program.  
FLS 11/19/02

rm.htm

3/12/02