

COMPAQ
COMPUTER CORPORATION

Remington Arms Co.
ARMS SERVICE DIVISION
UPSTAIRS
14 HOEFER
ILLINOIS, NY 13357
ATTN: DENNIS SAWYER

Mike W. Loudamy at the Chevy Dealership explained that this is not the first vehicle he has seen that was damaged due to a Remington Rifle discharging after the Safety Mechanism being placed from Safety to Fire without a finger on the trigger.

It is very fortunate that no one was injured or killed when the gun discharged from moving the Safety Mechanism from Safety to Fire. I still think about what could of happened had the transmission torque converter not stopped the bullet.

What I am looking for by sending my GUN to your attention is to make sure that this GUN is thoroughly tested so the safety mechanism does not result in the GUN discharging ever again without my finger near the trigger. As I explained in the beginning, I have been hunting and target shooting with Remington Fire Arms for over 18 years and never had a GUN discharge by moving the Safety Mechanism from Safety to Fire. It is clear that the Safety Mechanism caused my gun to fire and I think Remington should be responsible for the damages that resulted from a faulty Safety Mechanism causing the GUN to discharge.

Please contact me once you receive the Fire Arm. Thank you for your immediate attention and cooperation ahead of time. I have reported this to my insurance company and I am sure that they will be in touch with you.

Sincerely,

A handwritten signature in cursive script that reads "Rodney C. Turpin".

Rodney C. Turpin