

Date: December 10, 1997

Dear Remington:

I purchased a Remington 700ML from AlderRun Gun Shop in Franklin Vt. I was hunting in the mountains on Sunday Dec 6. After sitting for awhile I decided to see how loud the safety was by putting to the fire position. The gun discharged. Thinking I had my finger on the trigger, I then cocked the gun and tried empty, the bolt went forward. It did this several times until the gun was warmed, then it no longer happened. Alder Run says he had one last year that did the same thing. These are the conditions we hunt in with muzzle-loaders. I'm not asking for this gun to be repaired but inspected by your facility to see what can be defected with the safety. Oh we can say cleaning or weather but we all know they still should be safe. I'm asking for a credit toward another firearm, I do not want this one returned. I will take a Model 700 mountain rifle and I'm willing to pay the differents. Caliber 30-06. I currently own many remington firearms and have never had any problems. A little bit of history about myself;

- 1) Hunter Education Instructor for St of Vt.
- 2) Hold record for largest buck ever taken in Vt with a muzzleloader.
- 3) Corporate Quality Director for a major company.
- 4) Bagged 39 deer.

Please honor my request for trading.

Thank-You

erry Tatro
Golf Course Rd
Whford Vermont 05476

848-3387

P.S.

I did Not have the Proper
Tools To Remove Scope Mounts

received
1-8-98