January 3, 1991

Ronald Verser 50 Harver Hills Malvern, Ar. 72104

Remington Arms Inc. Arms Service Division Ilion, My. 13357

RF: Inspection and repair on Model 650 rifle, SN# 6210107, Cal .308

State of the second

Dear Arms Service Department;

I am returning my rifle for inspection, and service or repair, as per phone conversation with one of your representatives.

In early December this past year the rifle discharged while I was chambering a round, as best as I can remember the bolt was not completely locked down. Ipromptly unloaded it and have not tried it again to see if the same thing would happen.

I bought the rifle new about twenty years ago and have only had it to the gunsmith one time during that period of time. That one time occured some time back when I read of a recall for this model rifle, I took it to a local gunsmith who checked it and said that according to the serial number that it wasn't affected by the recall.

If there are any questions, I can be reached at my home phone most weekdays from 9 am. until about 11 am. at (5/1) 337-4339. If there are any charges please bill me at the above address.

Timestely, /
Yonald Vister
Lonald Verser

FROM: Ronald Verser

30 Halver Hits

MAINERN, AR 72104

Kemington ARMS Inc.

ARMS Service Sivision

Ilian, Ny, 13357