

Repair Order Number



Repair Order Number RE00054570	Description/Serial Number B6339840	Repairman - Dale Lewis
Account # - R-	Model 700 Center Fire Caliber: 3006	Date Received - 11/11/2002
	BDL	Estimate Date - 10/30/2002
		Current Date - 11/12/2002
Customer KEITH VERDEN 8505 MILLWAY DRIVE AUSTIN, TX 78757 US		Return To KEITH VERDEN 8505 MILLWAY DRIVE AUSTIN, TX 78757 US
Phone (H) (512)-459-8330	Fax (512)-454-4079	
Phone (W)	Email KVIRDEN@HELLERIN	

Problems			
Reported		Round	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	FIRES WHEN TAKEN OFF SAFE		

Repair					
Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
4000119	GR-TEST	1	1	0	Y
4000294	GR-CHECK TPA	1	1	0	Y
Service Total:		22	22	0	

Condition	REC'D W/ WOOD MARS.				
Problem/Notes	adjustment screws altered,replace trigger assem \$20 per product service				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date